NTSB ID: DEN02GA102 Aircraft Registration Number: N24GS

Occurrence Date: 09/04/2002 Most Critical Injury: Fatal

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Airport Proximity: Off Airport/Airstrip	Distance From	I m Landing Facility:		Direction Fro	m Airport:	
Howard	со	81233	0656	MDT		
Nearest City/Place	State	Zip Code	Local Time	Time Zone		

Aircraft Information Summary

Aircraft Manufacturer	Model/Series	Type of Aircraft						
Cessna	A185F	Airplane						

Sightseeing Flight: No

Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

HISTORY OF FLIGHT

September 4, 2002, at 0656 mountain daylight time, a Cessna A185F, N24GS, was destroyed when it impacted terrain while maneuvering near Howard, Colorado. The commercial pilot was fatally injured, and his passenger was seriously injured. The State of Colorado's Division of Wildlife (DOW), was operating the airplane under Title 14 CFR Part 91. Visual meteorological conditions prevailed for the local aerial fish stocking flight which originated approximately 20 minutes before the accident. No flight plan had been filed.

DOW employees said that the pilot was scheduled to do an aerial fish drop in Hunt Lake (elevation 11,300 feet). He departed Salida, Colorado (elevation 7,489 feet), with a fish hatchery employee as an operations observer. Flight data retrieved from an onboard GPS unit indicates that the airplane flew directly towards the lake and circled two times over Howard, Colorado, while gaining altitude. At 0652:30, the airplane was at 11,429 feet, and on a 250 degree true heading. At 0655:16, the airplane was on a 245 degree true heading and descending at approximately 360 feet per minute. The airplane impacted a ridge, approximately 90 degrees to its left, 5 to 10 seconds later. The last GPS location was approximately 350 feet from the impact site, and approximately 100 feet above it.

The injured passenger said that he remembered the flight towards Hunt Lake, but his last recollection was "Jim [the pilot] was pulling back real hard on the steering wheel." He said that when he regained consciousness he smelled fuel vapors, and he exited the airplane.

An emergency locator transmitter signal was received at approximately 0.750 by other DOW pilots. The airplane was located approximately 1 hour later.

PERSONAL INFORMATION

The pilot took his last second class Federal Aviation Administration (FAA) flight medical examination on May 1, 2002, and at that time he reported on his application that he had 7,400 hours of flight experience, with 200 hours during the last 6 months. He renewed his flight instructor's certificate on August 21, 2001. The pilot had been flying for the State of Colorado DOW for approximately 20 years.

AIRCRAFT INFORMATION

The airplane was a single engine, propeller-driven, fixed gear, two seat airplane, which was manufactured by Cessna Aircraft Company in 1976. It was powered by a Continental IO-520-D, six cylinder, reciprocating, horizontally opposed, direct drive, air cooled, normally aspirated (carbureted) engine with a maximum takeoff rating of 300 horsepower at sea level. At a density

NTSB ID: DEN02GA102

Occurrence Date: 09/04/2002

Occurrence Type: Accident

Narrative (Continued)

altitude of 12,350 feet, an engine manufactures representative said it would have been capable of producing approximately 165 horsepower. Aircraft maintenance records indicate that the last annual inspection was accomplished on April 5, 2002. The airplane's tachometer and maintenance records indicated that it had accumulated approximately 9,017 hours of flight time, and the engine had approximately 570 total hours since new.

The airplane was modified with an airborne fish stocking tank, that was divided into nine compartments. Each compartment had a 5 gallon capacity; the fish were fingerlings in size. The tank held approximately 400 pounds of water, and approximately 3 to 4 pounds of fish. Each compartment could be released individually, and the best release altitude was approximately 100 feet above the water.

METEOROLOGICAL INFORMATION

At 0650, the weather on Monarch Pass, Colorado, (elevation 12,030 feet) 280 degrees 22 nautical miles (nm) from the accident site, was as follows: wind 240 degrees at 19 knots; visibility 10 statute miles; clear of clouds; temperature 39 degrees Fahrenheit; dew point 34 degrees Fahrenheit; altimeter setting 30.73 inches. The other three DOW pilots reported that the wind was calm at Salida, Colorado, at the time of their takeoffs. The sunrise was 0636 on the morning of the accident.

The first of the four pilots to depart Salida reported that he encountered (approximately 15 nm from Hunts Lake) a sudden wind gust of approximately 20 to 25 knots at 240 degrees when he reached 12,500 feet. The other two pilots reported encountering occasional downdrafts and wind shears, with occasional moderate turbulence between 11,500 to 12,500 feet.

The density altitude was calculated to be 12,350 feet at the accident site.

WRECKAGE AND IMPACT INFORMATION

The airplane was found (N38 degrees, 23.63'; W105 degrees, 56.10'; elevation 11,662 feet) on a narrow high mountain ridge (elevation 11,662 feet). The ridge was oriented approximately 040-220 degrees, and was lightly forested with 20 to 70 foot conifers. The upper portions of several trees were found on the ground. A ground scar led to the airplane on a 130 degree heading. The airplane was found slightly inverted on its left side. The right wing's outboard 3 feet was separated, and the remainder of the wing was still in place. The left wing was nearly separated from the fuselage, and it was folded back and under the fuselage.

All of the airplane's major components were accounted for at the accident site. The flight control surfaces were all identified, and flight control cable continuity to all control surfaces could only be partially confirmed due to impact damage. The fuselage was bent and crushed, and its cabin volume was slightly reduced. The original shape of the cabin was not maintained. Both main landing gear had separated from fuselage; the tail wheel was still attached to the empennage.

The engine (with all of its accessories) was in place, but attached to the fuselage by only cables and cowling material. Engine continuity was established through the drive train; thumb compression was noted on all of the cylinders, except the number four cylinder. This cylinder was removed and metal debris was found under the intake valve. The debris matched a 1.5 inch hole in the number four cylinder intake pipe. The propeller hub assembly remained attached to the crankshaft flange. Blade 1 was bent 140 degrees toward the cambered side. It was loose in the hub. Blade 2 was twisted toward the direction of rotation. Both blades exhibited scoring, and leading edge and tip damage.

No preimpact engine or airframe anomalies, which might have affected the airplane's performance, were identified. There was no evidence of postimpact fire.

NTSB ID: DEN02GA102

Occurrence Date: 09/04/2002

Occurrence Type: Accident

Narrative (Continued)

MEDICAL AND PATHOLOGICAL INFORMATION

An autopsy was performed on the pilot by the El Paso County Coroner, Colorado Springs, Colorado, for the Fremont County Coroner, Salida, Colorado.

The FAA's Civil Aeromedical Institute (CAMI) in Oklahoma City, Oklahoma, performed toxicology tests on the pilot. According to CAMI's report (#200200241001), the blood was tested for carbon monoxide, cyanide, and drugs, with negative results. The pilot's vitreous was tested for volatiles (ethanol) with negative results.

ADDITIONAL DATA

The airplane, including all components and logbooks, was released to a representative of the owner's insurance company on October 10, 2002.

NTSB ID: DEN02GA102

Occurrence Date: 09/04/2002

AVIATION	Occurrence Type: Accident										
Landing Facility/Approach In	formation	•									
Airport Name			Airport ID:	Airport Eleva	tion	Run	way Used	Runwa	y Lengt	h R	unway Width
				Ft	. MSL						
Runway Surface Type: Unknown				l							
Runway Surface Condition: Unknown											
Type Instrument Approach: Unknown	- own										
VFR Approach/Landing: Unknown	1										
Aircraft Information											
Aircraft Manufacturer				l/Series						Number	
Cessna			A185	5F 					185-0	03093	
Airworthiness Certificate(s): Normal											
Landing Gear Type: Tailwheel											
Homebuilt Aircraft? No	Certifie	Certified Max Gross Wt. 335					50 LBS Number o		nes: 1		
				Engine Manufacturer: Model/Series: IO-520-D							ated Power: 300 HP
- Aircraft Inspection Information											
Type of Last Inspection			Date of Last Inspection Time Since			nce Last Inspection			Airframe	Total Time	
Annual			04/2002	04/2002 111 Hours					urs		9017 Hours
- Emergency Locator Transmitter (ELT) Information	•							•		
ELT Installed? Yes	ELT Operat	ted? Ye	S		ELT	Aided i	n Locating Ac	cident S	ite? Ye	s	
Owner/Operator Information	-										
Registered Aircraft Owner			Street	Address 6060 Bro	nadwa	v					
State of Colorado	City								Zip Code		
	<u> </u>	Denver CO 80216									
Operator of Aircraft Street Address Same as Reg'd Aircraft Owner											
Same as Reg'd Aircraft Owner	City							State	Zip Code		
Operator Does Business As:				То	perator Desig	nator Co	de:				
- Type of U.S. Certificate(s) Held: None											
Air Carrier Operating Certificate(s):											
Operating Certificate: Operator Certificate:											
Regulation Flight Conducted Under: Part 91: General Aviation											
Type of Flight Operation Conducted		ai Avial									
- 1750 or 1 light Operation Conducted											
		FACTU	JAL REPO	ORT - AVIAT	ION						Page 2

NTSB ID: DEN02GA102

Occurrence Date: 09/04/2002

1-		7 × 1	00,0 1,202										
AŊ	Occurrence Type: Accident												
First Pilot Informa	ation												
Name						City				State	D	ate of Birth	Age
On File						On File	le On File On File 57						57
Sex: M Seat Oo			Ce	rtificate	Numbe	er: On File							
Certificate(s): Flight Instructor; Commercial													
Airplane Rating(s): Multi-engine Land; Single-engine Sea													
Rotorcraft/Glider/LTA: None													
Instrument Rating(s)	Airpla	ane											
Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine; Instrument Airplane													
Type Rating/Endorse	ement fo	or Accident/In	cident Aircraf	ft?			Current	Bienn	ial Flight F	Review?			
Medical Cert.: Class	2	Medica	al Cert. Status	: None					Date of La	ast Med	ical Exa	am: 05/2002	
- Flight Time Matrix		All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Actu	Instrument Simulate		Rot	torcraft	Glider	Lighter Than Air
Total Time		7600											
Pilot In Command(PIC)													
Instructor													
Last 90 Days													
Last 30 Days													
Last 24 Hours		1	1	1							1		
Seatbelt Used? Yes		Shou	lder Harness	Used? Yes		T	oxicology P	erforn	ned? Yes		Sec	ond Pilot?	
Flight Plan/Itinera)r)/												
Type of Flight Plan F		ompany VFI	 R										
Departure Point	1	, , ,					State	Airpo	ort Identifie	er I	Departu	ure Time	Time Zone
Salida						c	Ю	0V2			0741		MDT
Destination State Airport Identifier													
Local Flight													
Type of Clearance: Unknown													
Type of Airspace: Class G													
Weather Information													
Source of Briefing: Company; National Weather Service													
Method of Briefing: Telephone													
	FACTUAL REPORT - AVIATION Page 3												

NTSB ID: DEN02GA102

Occurrence Date: 09/04/2002

A TYBOA			(Occurrence Type: Accident										
Weather	Information													
WOF ID	Observation Time	Time Zone	WC	OF Elevati	ion	WOF D	WOF Distance From Acciden				Direction Fron	n Accident Site		
MANAD	0050	, ADT		10000 F					00 1114			000 D 1	\ 4	
MYP	0650	MDT		12030 Ft.	MSL				22 NM			280 Deg. I	viag.	
Sky/Lowes	st Cloud Condition: Clea	r					Ft. A	AGL	Condition of Light: Day					
Lowest Ce	iling: None			Ft.	AGL	Visib	oility:	10	SM	M Altimeter: 30.73			"Hg	
Temperatu	ure: 4 °C	Dew Point:		1 °C	Wind	Direction	: 240			Der	nsity Altitude:	12350	Ft.	
Wind Spee	ed: 19	Gusts:			Weath	ner Cond	tions at Ac	cident S	ite: Visual C	Cond	itions			
Visibility (F	RVR): Ft.	Visibility	y (RVV)		SM	Intensit	ty of Precip	oitation:						
Restriction	s to Visibility: None													
Type of Pro	ecipitation: None													
Accident Information														
Aircraft Dai	mage: Destroyed		А	ircraft Fir	e: None)			Aircraft Exp	losio	n None			
Classificati	ion: U.S. Registered/U	.S. Soil												
- Injury Su	mmary Matrix	Fatal	Serious	Mino	or	None	TOTAL							
First Pi	ilot	1						1						
Second	d Pilot													
Studen	nt Pilot													
Flight I	nstructor													
Check	Pilot													
Flight E	Engineer													
Cabin A	Cabin Attendants													
Other Crew														
Passengers				1				1						
- TOTAL ABOARD - 1				1				2						
Other Ground				+				-						
- GRANE		1				2								
		1		<u>'</u>			<u> </u>							

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: DEN02GA102

Occurrence Date: 09/04/2002

Occurrence Type: Accident

Δc	m	ınıc	trativa	Into	rmation
\neg	4111	เบเจ	uauve	HILL	ทากสแบบ

Investigator-In-Charge (IIC)

James F. Struhsaker

Additional Persons Participating in This Accident/Incident Investigation:

Brian Richardson FAA FSDO Denver, CO 80249